#### **DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-025464 Address: 333 Burma Road **Date Inspected:** 17-Jun-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** N/A **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG COMPONENT** 

### **Summary of Items Observed:**

On this day Caltrans OSM Quality Assurance (QA) Inspector Subhasis Bera was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhen Hua Port Machinery Company (ZPMC) at Chang Xing Island in Shanghai, China. QA Inspector observed and/or found the following:

Magnetic Particle Testing (MPT) for Segment 14E at bay#14

This Quality Assurance (QA) Inspector performed Visual inspection, witness and verification of Magnetic Particle Testing (MT) 15% for OBG segment 14E component at bay#14. This QA inspector generated a (MT) report for this date .This area was previously tested and accepted by ZPMC QC MT technicians.

The Weld Designations are as follows

SEG3019BB-047,48,069,259~261,268~271,091,085,070,071,107,113~115,129,135 SA3359-001-020 SEG3019BC-015~020 SEG3019BC1-020,007,008,013,014 SA3360-001-019.020 SA3361-001-011,019,020

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

documents.

## **Summary of Conversations:**

No relevant conversations

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

<b>Inspected By:</b>	Bera, Subhasis	Quality Assurance Inspector
Reviewed By:	Dsouza, Christopher	QA Reviewer